





# **HANUL** Meeting

January 29, 2020


### Single PE Trimmer

Board type		New HTOF	E42 BH2
Trimmer value	100K 2M	2M	100K
SPE Adjust	yes	yes	no

- New HTOF uses 2M for trimmer.
- Old giga trimmer's ACTUAL VALUE was 2M(100K in the circuit diagram).
- 1M trimmer is under ordering from *Eleparts* to test with BH2 board.(No 2M with same footprint)



#### E42 BH2 Crosstalk









Figure: Scintillator signal(Blue) vs Crosstalk signal(Purple)



#### Cause of the Crosstalk










Figure: Board Geometry; Black regions are the conductor.

 The ground of MPPCs are shared.

# No crosstalk case(Almost zero, $\leq 5\%$ )

